


# UXP-XXX-38S-01

For 3/8" Superflexible Connectors



	Connector models supported			
	Interface	4.3-10	Nex10	2.2-5
	Male	UXP-4MT-38S-01	UXP-1MT-38S-01	UXP-2MT-38S-01
	Female	UXP-4F-38S-01		
	Male push-pull			
	Right angle	UXP-4RT-38S-01	UXP-1RT-38S-01	UXP-2RT-38S-01



Scan for installation video

## Tools/materials required

Power drill	SP-38S-01 Prep/strip tool	HCG-CC (RP240 / RP210-B / RP100-B)	Frameset	TQ-78-F8 4.3-10	TQ-716-F3.7 Nex10	TQ-916-F6 2.2-5
			 Refer to Step #3			
T-Handle	RDCUTTER-S	SP-CC	SP-PLV	Adjustable Wrench	Alcohol wipe (included with connector)	
						

## Step #1: Prep



Straighten cable. Using RDCUTTER-S, apply even pressure while rotating tool around cable to cut off cable squarely.


Optional: If using the JMA Weather Protection System (WPS), follow the WPS instruction manual for proper installation before proceeding to Step #2.




Attach prep/strip tool SP-38S-01 to drill.



Actuate drill to remove jacket and expose center conductor. Then remove cable from tool.




Proper prep is achieved when center conductor is chamfered as shown.



Use the "J" coring bit that comes with the prep tool to remove dielectric until the cable bottoms on the bit. Alternately, a drill can be used in place of the T-Handle.




Use center conductor cleaner, SP-CC tool, to remove any remaining dielectric material on center conductor.



For plenum cable, insert the prepped cable end at a downward angle into the SP-PLV, tapping the cable while vacuuming.

### Cable preparation guide

Compare to picture to determine if correct cable prep was performed. (For reference only)



# UXP-XXX-38S-01

For 3/8" Superflexible Connectors



## Step #2: Install



Align outer conductor as shown with the etched line. Mark cable jacket (using pen or marker) in line with end of connector.



Use the alcohol wipe to clean the inner and outer conductors thoroughly.



Thread connector onto cable until it reaches alignment mark and the connector bottoms on the cable.

**⚠** JMA 3/8" Superflex connectors contain a clutch mechanism to prevent over-tightening of the connector onto the cable. This also means when the connector is fully installed on the cable prior to compression, the connector will continue to spin freely when twisted, without damaging the cable.

## Step #3: Frameset options



## Step #4: Compress



Pull/push back frameset to allow connector/cable to lay flat in the frame.



Make sure connector is fully seated. Press HCG trigger until compression tool cycles. Do not pull or push on tool during compression.



When fully compressed, connector will move away from alignment mark.

## Step #5: Torque



Mate the connector to the port, using the proper torque from the table to the right. When not attaching to a port, make sure the mating connector is supported by an adjustable wrench.

Proper torque		
Series	Torque	Hex nut size
4.3-10	8 lbf·ft (10.85 N·m)	7/8" (22 mm)
Nex10	3.7 lbf·ft (5.0 N·m)	7/16" (11 mm)
2.2-5.0	6 lbf·ft (8.13 N·m)	9/16" (16 mm)
<b>Note:</b> 4.3-10 push-pull connectors (4MP) do not require the torque step.		